



REPORT ON  
RESOURCE AND POTENTIAL RECLAMATION  
EVALUATION  
OF  
  
CHROMO/4 STUDY SITE  
OTTER CREEK COALFIELD  
MONTANA  
1978

UNITED STATES · DEPARTMENT OF THE INTERIOR · BUREAU OF LAND MANAGEMENT  
AND  
BUREAU OF RECLAMATION



#4757582  
IDS801909

TD  
195  
575  
E47  
M46  
c.3

BLM LIBRARY  
SC-324A, BLDG. 50  
DENVER FEDERAL CENTER  
P. O. BOX 25047  
DENVER, CO 80225-0047

RESOURCE AND POTENTIAL RECLAMATION EVALUATION

OF  
CHROMO/4 STUDY SITE  
OTTER CREEK COALFIELD, MONTANA

Bureau of Land Management  
Library  
Bldg. 50 Denver Federal Center  
Denver, CO 80225

## CONTENTS

	<u>Page</u>
Introduction-----	1
Purpose-----	1
Authority-----	1
Location-----	1
Climate-----	2
Physiography-----	4
Geology-----	5
Regional Geology-----	5
Site Geology-----	6
Investigations-----	6
Stratigraphy-----	7
Structure-----	8
Paleontology-----	8
Engineering Geology-----	8
Coal Resources-----	9
Coal Analysis-----	9
Estimation of Coal Resources-----	9
Land Classification-----	11
Description of the Land-----	11
Alluvial Soils-----	11
Colluvial Soils-----	11
Residual Soils-----	12
Description of Classes-----	12
Methods and Procedures-----	13
Results of Classification-----	13
Soil Inventory-----	14
Reclamation Potential-----	14

## PLATES

	<u>Follows</u>	<u>Page</u>
Plate 1 - General Location Map-----	2	
Plate 2 - Geologic and Investigations Map-----	6	
Plate 3 - Geologic Log of DH77-101-----	6	
Plate 4 - Overburden Thickness Map-Knoblock Coalbed-----	10	
Plate 5 - Semi-Detailed Land Classification-----	14	
Plate 6 - Topsoiling-----	14	
Plate 7 - Subsurface Material-----	14	
Plate 8 - Soil Survey Map-----	14	

TABLES

Follows Page

Table 1 - Potential Consumptive Use of Moisture and Available Moisture-Native Grasses-----	2
Table 2 - Coal Analyses-----	10
Table 3 - Coal Reserves, Overburden, Interburden Volumes & Ratios, Acres & Tons per Acre-----	10
Table 4 - Land Classification Specifications-----	12
Table 5 through 8 - Erosion Evaluation and Soil Profiles-----	Appendix
Table 9 ( 10 sheets ) - Laboratory Analyses-----	Appendix

PHOTOGRAPHS

Photographs 1 through 3-----	4
------------------------------	---

RESOURCE AND POTENTIAL RECLAMATION EVALUATION  
OF  
CHROMO/4 STUDY SITE  
OTTER CREEK COALFIELD, MONTANA

INTRODUCTION

The nation's ever increasing need for energy has focused attention on the abundant low sulphur coal resources in the Western States, primarily the Rocky Mountain and the Northern Great Plains regions, due to the abundance, ease of extraction, and the quality of the coal present. It is the responsibility of the Bureau of Land Management to assist in meeting the nation's energy demands and, at the same time, provide for reclaiming surface mined lands.

Purpose

This study will provide data for developing reclamation objectives at a potential coal leasing area. The site was selected to determine if existing data collected for the nearby Otter Creek Study Site (EMRIA No. 1) could be correlated or projected throughout the Otter Creek Coalfield.

Authority

This report is prepared in accordance with Section 4 of the Agreement between the Bureau of Land Management and the Bureau of Reclamation dated May 7, 1974.

Location

The Chromo/4 Site is located in Powder River County, about 12 miles (19.4 km) southeast of Ashland, Montana. The site includes all of Section 4, T. 5 S., R. 45 E. It is 1.5 miles (2.4 km) southwest of the Otter Creek East Study Site which was completed in 1976. Plate 1 shows the general location of all study sites in the Otter Creek Coalfield.

The Federal Government owns all coal deposits in the site. The surface is privately owned.

## CLIMATE

The Chromo/4 Study Site is in the Otter Creek geographical area which has a continental-type climate. It is cold in the winter, warm in the summer and large daily variations are common. Elevation at the site ranges from 3155 (961) to 3400 ft. (1036 m). The Broadus weather station at elevation 3030 ft. (924 m) receive an average of 14.2 inches (361 mm) of precipitation annually and Birney, at elevation 3190 ft. (973 m) receives an average of 13.7 in. (348 mm) annually. Torrential rainstorms are common and unprotected soil surfaces may erode severely during these storms. These storms, though common, may not cover large areas. Hailstorms occasionally cross the area, but these weather extremes do not place the area in any particular type storm belt. About 53 percent of the precipitation falls as rain during the growing season. Growth of native range is rapid during May and June which are the wettest months of the year. Precipitation data from the Otter weather station 27 miles (43.5 km) southwest of this site follow:


						Percent of	
May	June	July	August	Sept.	Annual	Annual	
2.51	3.30	1.32	1.26	1.69	53	19.10 <sup>1/</sup> inches	
63.8	83.8	33.5	32.0	42.9	53	485.1 millimeters	

The elevation of the Otter station is 4000 ft. (1219 m).

The frost-free period (32°F or 0°C) ranges from 108 days at Birney to 120 days at Broadus. The growing season for hardy grasses (28°F or -2.2°C) in average years begins May 10 at Birney and ends 131 days later on September 19. Following the spring rains, July is hot, dry and windy with excessive evaporation and evapotranspiration rates. Humidity is low. During the months of June, July and August, about 32 days have a temperature of 74°F (23.3°C) or higher. Average monthly temperatures exceed 51°F (10.6°C) in May, June, July, August, September and October. July with an average temperature of 74°F (23.3°C), is the hottest month and May and October with 51°F (10.6°C) are the coolest growing season months.

The climate in the Otter Creek area in most years is suited for reclamation of surface-mined land because the spring rains are generally adequate for establishing stands of native vegetation. The 13.7 (348) to 14.2 in. (361 mm) of precipitation received in average years meet the requirement of range vegetation which grows rapidly in the late spring and early summer. This moisture from natural precipitation is usually depleted by established native grasses in 6 to 8 weeks and the plants mature and become dormant. Consumptive use data in Table 1 show native grasses could use 22.5 inches (572 mm) of moisture if

1/ The Otter station is several hundred feet higher than this study site. The apparent effect is an increase in the precipitation especially during the nongrowing season.



GENERAL LOCATION MAP  
FOR  
OTTER CREEK COALFIELD  
STUDY SITES

Multiply miles by 1.6093 to obtain kilometers



Table 1 - Potential Consumptive Use of Moisture and Available Moisture - Native Grasses 1/

## Chromo/4 Study Site

<u>Month</u>	<u>Midpoint</u>	<u>Accumulative Days to Midpoint</u>	<u>Air Temp. (°C)</u>	<u>Monthly Requirement Millimeters</u>	<u>Moisture Reserve Millimeters 2/</u>	<u>Precipitation Millimeters</u>	<u>Difference 3/ Millimeters</u>
May 4	May 17	13	12.6	71.1	+ 102.6	56.6	+ 88.1
June	June 15	42	17.3	120.6	+ 85.6	79.5	+ 47.0
July	July 15	72	21.8	161.5	+ 47.0	34.5	- 80.0 4/
August	August 15	103	21.0	140.2	- 80.0	27.4	- 192.8
Sept.	Sept. 13	131	14.6	77.5	- 192.8	30.5	- 239.8
Sept. 27		145					
				570.9		228.5	

1/ Computed by Blaney-Criddle Method using the Broadus Weather Station - Latitude 45°26' N.

2/ Moisture Reserve = Summation of precipitation (Oct. to April) = 128.3 x 0.80 = 102.6 millimeters

3/ Difference = Moisture Reserve plus precipitation minus moisture use

4/ Natural precipitation during most years is inadequate to meet potential moisture needs. In average years, the plants use the available moisture by July 15 and mature and become dormant.

Table 1




available; but it also shows that 13.9 inches (353 mm), or the average annual precipitation could be used by July 15. Table 1 prepared for the Otter Creek Study Site also represents the potential consumptive use in this site.

Reclamation of surface-mined land is very difficult in areas that consistently receive 10 in. (254 mm) or less of precipitation each year. In this area, years that receive less than the average annual precipitation are not common. The Broadus station reported less than 10 in. (254 mm) only three times in the last 37 years and Birney only once in the last 21 years.

## PHYSIOGRAPHY

The Chromo/4 Study Site is in the unglaciated portion of the Great Plains physiographic province. Relief in the area ranges from 3755 ft. (961 m) on Chromo Creek in the eastern part of the area to over 3400 ft. (1036 m) in the southwestern part of the section. Topography varies from flat to gentle slopes along parts of the Chromo Creek Valley floor to a steep semi-badland type at the higher elevations where erosion of the underlying soft shale and weakly cemented sandstone has been severe. Drainages in the area have developed along a dendritic pattern leading into Chromo Creek which trends easterly to Otter Creek, a tributary of the Tongue River. Photographs 1 through 3 show the typical terrain in the study site.



Photograph 1 - Chromo/4 Study Site - Otter Creek Coalfield, Montana. Panoramic view looking west into the study site. Photograph was taken from trail in eastern part of Section 4.

U. S. Bureau of Reclamation photograph

11/16/77





Photograph 2 - Chromo/4 Study Site - Otter Creek Coalfield, Montana.  
View of sandstone capped butte in southwest quarter of Section 4, T. 5 S.,  
R. 45 E. Odell (?) clinker crops out about halfway up scarp.  
U. S. Bureau of Reclamation photograph

11/16/77



Photograph 3 - Chromo/4 Study Site - Otter Creek Coalfield, Montana.  
View looking downstream into the ravine in the northeast quarter of  
Section 4, T. 5 S., R. 45 E. Photograph taken from Drill Hole 77-101.  
U. S. Bureau of Reclamation photograph

11/16/77



## GEOLOGY

### Regional Geology

The Chromo/4 Study Site is located in the northern part of the Powder River Basin in southeastern Montana. This basin, a part of the unglaciated portion of the Great Plains physiographic province, is about 225 miles(362 km) long, extending from the Yellowstone River in Montana to the North Platte River in Wyoming. It is about 90 miles(145 km) in width, bounded on the west by the Bighorn Mountains and on the east by the Black Hills. Structurally, the basin is an asymmetrical syncline with a northwestward trending axis. An estimated 18,000 feet(5486 m) of sediments overlie the basement complex in the deepest part of the basin north of Glenrock, Wyoming.

The geologic history of the area since Precambrian time includes periods of deposition, deformation, and erosion. During the Paleozoic and Mesozoic Eras, a sequence of carbonates, sandstones, and shales was deposited throughout Montana and Wyoming. Thickness of these sediments on the west side of the basin varies from 9,000 feet(2743 m) near Yellowtail Dam to 11,500 feet(3505 m) near Buffalo, Wyoming. About 6,500 feet(1981 m) of Paleozoic and Mesozoic sediments are present in the Black Hills area on the east side of the basin.

The area was relatively stable during these periods with deposition usually occurring in a marine environment. Deformation of strata began with the Laramide Revolution near the close of the Mesozoic Era (Late Cretaceous), at which time mountain masses such as the Bighorns and Black Hills were uplifted. Uplift continued throughout Paleocene and gradually ended in Eocene time. Materials stripped from the mountains were deposited in fans or sheets across the basin floors, gradually burying the flanks of the mountains in their own debris. By the middle of the Cenozoic Era, the basins were largely filled and the mountains peneplaned. In Pliocene time, a broad regional uplift occurred and continued intermittently into Pleistocene time. This uplift raised the previously developed peneplain surface to elevations of about 10,000 feet (3048 m) in the Bighorn Mountains. Streams rejuvenated by the uplift excavated the basins and exhumed the buried mountain masses.

Today, Precambrian rocks are exposed in the cores of the Black Hills and Bighorn Mountains. These rocks are surrounded by sediments of Paleozoic and Mesozoic Age. The central part of the basin is filled with Cenozoic (Tertiary) sediments.

## Site Geology


### Investigations

Previous geologic investigations have been conducted in the general area by the U. S. Geological Survey and the Montana Bureau of Mines and Geology. A list of relevant maps and publications follows:

1. U.S.G.S. Bulletin 1072-J - Reconnaissance Geology of the Birney-Broadus Coal Field, Rosebud and Powder River Counties, Montana.
2. U.S.G.S. Miscellaneous Field Studies Map MF-802 - Willow Crossing Quadrangle, Montana.
3. U.S.G.S. Miscellaneous Field Studies Map MF-807 - Fort Howes Quadrangle, Montana.
4. U.S.G.S. Miscellaneous Field Studies Map MF-814 - Browns Mountain Quadrangle, Montana.
5. U.S.G.S. Miscellaneous Field Studies Map MF-817 - King Mountain Quadrangle, Montana.
6. Montana Bureau of Mines and Geology Bulletin 69 - Strippable Coal Deposits on State Land Powder River County, Montana.
7. Montana Bureau of Mines and Geology Bulletin 91 - Quality and Reserves of Strippable Coal, Selected Deposits, Southeastern Montana.

Geologic investigations were conducted at the Chromo/4 Study Site by the U. S. Bureau of Reclamation during November and December of 1977. Investigations included mapping the surface geology and drilling one core hole. Drill cores were tested by the U.S.B.R. Soils Laboratory for suitability in reconstructed profiles. Results of the tests are graphically shown on the geologic log. Detailed geologic mapping was done in the field on aerial photographs. The data were transferred to a topographic map and are shown on Plate 2. A detailed geologic log for Drill Hole 77-101 is included in this report (Plate 3).

Core drilling was performed using a Failing Model 314 rotary drill rig with an "H" series wire line core barrel. Water from Otter Creek was used as the drilling fluid. Test results conducted by the U.S.B.R. Soils Laboratory in Miles City, Montana, indicated that the total dissolved solids in the water supply was about 1900 parts per million (1900 mg/l).



## EXPLANATION

PALEOCENE

FT UNION FORMATION (TONGUE RIVER MEMBER) - Interbedded shale, siltstone, sandstone and coal

CLINKER - Baked shale, siltstone and sandstone of the Fort Union Formation produced by burning of the Knoblock coalbed. Up to 30 feet thick

Cooled burned at outcrop

A through G - Coal and/or carbonaceous shale beds

A - 2 to 3 ft. of coal and carbonaceous shale

B - 2 to 4 ft. of coal

C - Cooled burned at outcrop. Probably over 5 feet thick. Corresponds to Odell bed in U.S.G.S. bulletin 1072 J and Coche bed in U.S.G.S. Miscellaneous Field Studies Map MF-817

D - 2 to 4 ft. of carbonaceous shale

E - 2 feet of carbonaceous shale

F - 2 to 4 ft. of coal. Probably corresponds to A and C beds in Otter Creek Study Site (EMRIA #1) and to bed F in Otter Creek East and Dam Creek Study Sites

F<sub>1</sub> - 3 ft. + of carbonaceous shale. Minor water seeps occur along this bed at locations marked by

G - Base of Middle Bench of Knoblock Coalbed

DH 77-101 USBR Drill hole

P 1455 Drill hole from USGS Miscellaneous Field Studies Map MF-817

1000 0 1000 2000 3000  
SCALE OF FEET



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF RECLAMATION  
RESOURCE & POTENTIAL RECLAMATION EVALUATION  
CHROMO/4 STUDY SITE  
OTTER CREEK COALFIELD - MONTANA

## GEOLOGIC AND INVESTIGATIONS MAP

GEOLOGY G. TAUCHER SUBMITTED  
DRAWN WILLIE ALLSOP RECOMMENDED  
CHECKED                    APPROVED

BILLINGS, MONTANA

APRIL 1978

1305-600-146

NOTE  
Multiply feet by 0.3048 to obtain meters



GEOLOGIC LOG OF DRILL HOLE												SHEET 1 OF 3	
FEATURE	Chrom74 Study Area Otter Creek Coalfield	PROJECT	Work Order 005			STATE	Montana						
NOTE NO	77-101	LOCATION	1200' S. & 2550' E. of NW Ctnr. Sec. 4, T. 5 S., R. 45 E.	GROUND ELEV	3285±	DIP ANGLE FROM HORIZ.	Vertical						
BEGUN	11-15-77	FINISHED	12-2-77	DEPTH OF OVERBURDEN	--	TOTAL DEPTH	232.1'	BEARING	--				
DEPTH AND ELEV. OF WATER LEVEL AND DATE MEASURED		58.0'	(3227.1')	12-2-77	LOGGED BY	Parish	LOG REVIEWED BY			--			
NOTES ON WATER LOSSES AND LEVELS, CASING CEMENTING, CAVING AND OTHER DRILLING CONDITIONS		TYPE AND SIZE OF MOLE	CORE RECOVERY (%)	SOILS ANALYSIS SAMPLE	SUITABILITY FOR RECONSTRUCTED PROFILE	ELEVATION (FEET)	DEPTH (FEET)	GRAPHIC LOG	SAMPLES FOR TESTING	CLASSIFICATION AND PHYSICAL CONDITION			
				DEPTH (FEET)	SUITABLE	LIMITED SUITABILITY	UNUSABLE						
				FROM	TO								
<u>Drill</u>			100							1. FORT UNION FORMATION - PALEOCENE			
Falling 314 truck-mounted.				wash						0-0.7' TOPSOIL (WEATHERED SANOSTONE): About 85% fine sand; 15% nonplastic fines; strong HCl reaction; moist; crumbly to loose; scattered grass roots; tan to light brown (SM).			
<u>Drillers</u>										2. 0.7-14.6' SANDSTONE: Gray with rusty streaks; moist; uncemented; soft; crumbles easily; fine to medium grained; slightly laminated; bedding nearly horizontal; no HCl reaction; core lengths to 10".			
George Shaw Gerald Becker										NOTE: 1.5-11.0' logged from wash samples.			
<u>Method</u>										3. 14.6-22.0' SHALE: Gray with rusty streaks and bands; moist; firm; trims easily with knife; plastic; air slates; bedding nearly horizontal; very weak HCl reaction; core lengths to 18".			
Rx casing drive sample 0-1.5'. Rock bit wash samples 1.5-11.0'. Hq wireline core 11.0 to 232.1'. Reamed hole 0 to 40.5' with 6 1/2" rock bit to set 5" casing. Water and revert used as drill fluid. Lost 252 of water 23 to 35'. 100' water loss 35-134.5'. 902' loss 134.5 to 204.5'. 100% loss 204.5-213.1'. 902' loss 213.1-232.1'.				#1 0 22					4. 14.6-14.8' - Rusty, weathered concretion 19.5-20.3' - Joint dipping 80° 21.0-22.0' - Carbonaceous zone; core crushed and slickensided.				
<u>Casing Record</u>										5. 22.0-24.7' COAL: Black; damp; hard; brittle; badly broken; core lengths to 3".			
Set 5" casing to 40.5' 11-16-77 to try to prevent water loss. Casing was pulled on completion of hole.										6. 24.7-25.4' SANOSTONE: Light gray; damp; uncemented; crumbles with difficulty; fine grained; contains some silt; no HCl reaction; bedding not discernible; core lengths to 4".			
<u>Progress Record</u>										7. 25.4-35.0' SHALE: Light gray with rusty streaks varying to nearly black in one zone; damp; firm; difficult to cut with knife; bedding nearly horizontal; weak to strong HCl reaction; core lengths to 2".			
Depth	Date									8. 25.4-26.4' - Sandy, laminated. 26.4-28.0' - Carbonaceous; black; plastic; air slates; coal streaks 27.7 to 28.0'. 33.7-34.0' - Sandy; laminated; tan colored bands of fine sand.			
0-55'	11-15-77												
55-68.2'	11-16-77												
68.2-94.5'	11-17-77												
<u>Snow conditions in the area prevented further drilling until 11-29-77.</u>													
94.5-134.5' 11-29-77													
134.5-136.5' 11-30-77													
136.5-213.1' 12-1-77													
213.1-232.1' 12-2-77													
<u>Hole completion</u>													
Casing pulled and hole backfilled 12-2-77.													
<u>EXPLANATION</u>													
<b>CORE LOSS</b>	D = Diamond, N = Non-stellite, S = Shot, C = Churn P = Packer, Cm = Cemented, Cr = Bottom of casing E = 1-1.2", A = 1-7.8", B = 2-3.8", Ni = 3"** E = 7.8", A = 1-7.8", B = 1-5.4", Ni = 2-1.8"** E = 1-13.16", A = 2-1.4", B = 2-2.8", Ni = 3.1.2"** E = 1-1.2", A = 1-29.32", B = 2-3.8", Ni = 3"**												
<b>CORE RECOVERY</b>													

**NOTE:**

## SUITABILITY OF BEDROCK FOR RECONSTRUCTED PROFILES

SUITABLE- Can be used at or near the surface

LIMITED SUITABILITY- Should be placed in subsoil

UNSUITABLE- Should be buried below primary root zone

UNITED STATES  
 DEPARTMENT OF THE INTERIOR  
 BUREAU OF RECLAMATION  
 RESOURCE & POTENTIAL RECLAMATION EVALUATION  
 CROMO/4 STUDY SITE  
 OTTER CREEK COALFIELD - MONTANA



## Stratigraphy

The Fort Union Formation of Paleocene Age underlies the entire area. It is divided into the Tullock, Lebo and Tongue River Members. The Tullock and Lebo Members are not discussed in this report as they are not exposed and were not encountered in drilling. Except for alluvium, only sediments in the lower part of the Tongue River Member are involved in the study area. The upper part of the Tongue River and younger rock have been stripped away by erosion. Brief descriptions of the Cenozoic sediments involved in the site follow:

### Fort Union Formation (Paleocene)

Tongue River Member - pale olive to yellowish gray sandstone, siltstone, shale, carbonaceous shale and coal with thin lenticular calcareous or siliceous cemented concretions. Unweathered samples vary from light to dark gray in color. Poorly silicified, fragmented tree trunks and soft, calcareous shell fragments are common in zones. Sandstones, even though uncemented, tend to be resistant in outcrops. Shale and siltstone zones generally form slopes below sandstone ledges. Coal and carbonaceous beds are generally traceable over large areas. Conversely, correlation of clastic sediments over short distances is difficult due to variation in bedding thickness and lithologic changes. Tongue River sediments were deposited in a continental environment which included swamps conducive to the production of coalbeds. Thickness of this member varies from 1150 (350) to 1900 feet (579 m) in the Montana portion of the Powder River Basin.

One striking feature in the Tongue River Member is the resistant clinker zones that cap ridges or armor valley walls. The clinker, which is fused or baked rock, was produced by the burning of underlying coalbeds along their outcrops. In places where the heat was sufficiently intense, the clinker has been fused to a dark gray, lightweight rock similar in appearance to vesicular basalt. Near, the outer edge of thermal metamorphism, the rock is disoriented, baked and red to orange in color. Alteration of the overlying material is roughly proportional to the original thickness of coal that has burned. A coalbed 20 feet (6.1 m) thick will produce clinker zones 40 (12.2) to 60 feet (18.3 m) thick. The clinker is highly permeable and locally supplies water for springs and wells.

The most prominent clinker deposit near the study site was produced by burning of the Knoblock coalbed as shown on Plate 2. A second minor clinker produced by burning of the Odell coalbed, lies 150 (46) to 250 feet (76 m) above the Knoblock coal in the southwest part of the study site.

Only the Knoblock coalbed is of economic significance at the Chromo/4 Study Site. The Knoblock thins and splits into several benches between the Otter Creek Study Site (EMRIA No. 1) and the Chromo/4 and Dam Creek Study Sites, respectively located about 6 (9.6) and 7 miles (11.3 km) southward. For locations, see Plate 1. At the Otter Creek Study Site, the Knoblock averages about 61 feet (18.6 m) thick. At the Otter Creek East Site, a distance of 3(4.8) to 4 miles (6.4 km) southward, the Knoblock splits into an upper and lower bench, 45 (13.7) and 17 feet (5.2 m) thick, respectively. At the Dam Creek Site, about 2 miles (3.2 km) south of the Otter Creek East Site, the upper bench of the Knoblock thins to about 24 feet (7.3 m) thick and geologic data in the Montana Bureau of Mines and Geology Bulletin 91 indicates that lower benches of the Knoblock are insignificant. At the Chromo/4 Site, about 1½ miles (2.5 km) southwest of the Otter Creek East Site, the Knoblock splits into five main benches. In descending order they are about 6 (1.8), 26 (7.9), 7 (2.1), 2 (.6) and 10 feet (3 m) thick.

Alluvium (Holocene)— deposits of clay, silt, sand and gravel that cover valley floors of Otter Creek and its tributaries. Gravels are generally composed of clinker or hard shale and sandstone fragments. The deposits are up to 20 feet (6.1) thick.

#### Structure

Sediments at the Chromo/4 Study Site and in the surrounding Otter Creek Coalfield are generally flat lying with minor folding evident on the surface and on subsurface contour maps constructed using drill hole information. Some of the structural irregularities may be of a depositional nature while others may be due to differential compaction of the underlying strata.

Small local faults exist in the area as indicated by slickensides encountered in the drill core. They are generally restricted to weak, plastic carbonaceous shales immediately above or below coalbeds. Displacement along the fractures could not be determined but probably does not exceed 5 feet (1.5 m). No faulting was observed during surface mapping.

#### Paleontology

Occasional poorly silicified tree fragments and pieces of unidentified calcareous shells were found on the surface of the area. However, nothing of significance was observed.

#### Engineering Geology

Engineering property tests were not conducted on bedrock samples from the Chromo/4 Study Site. However, physical properties of these sediments should be similar to the results obtained for Fort Union samples at the Otter Creek Study Site (EMRIA Report No. 1) by the U. S. Geological Survey. Shear strengths of the materials are low, especially in a saturated condition.

Slides could easily develop adjacent to high walls in surface mines, namely along beds of weak, plastic, carbonaceous shales, which are typically cut by inherent slickensides. Adequate drainage should be insured to relieve porewater pressures in the overburden as mine excavations progress.

Saturated alluvial deposits and uncemented siltstones and fine grain sandstones will readily erode and flow into excavations. This problem is occasionally encountered in drilling when the walls of holes continue to collapse and slough. Depth of excavation below the water table will be limited until these materials are unwatered.

Excavation slopes will vary considerably between mine sites and will depend upon exposure time, moisture conditions, material types and depth of cut. Detailed engineering studies of the overburden will be required at each location for use in determination of designed slopes.

Studies conducted at the Otter Creek Study Site indicate that disturbed overburden (spoil banks and piles) should have slopes not greater than 4 to 1 with berms of 50 (15) to 100 feet (30.1 m) in width designed on the slope surface.

#### Coal Resources

##### Coal Analyses

The proximate, ultimate, Btu and sulfur forms analyses were completed by Northern Testing Laboratories in Billings, Montana, on one composite sample (DH77-101 at depths 143.9-149.7, 154.5-180.8, 182.0-188.9 and 215.3-225.6 feet or 43.9-45.6, 47.1-55.1, 55.5-57.6 and 65.6-68.8 meters) from the study site. Test results are shown Table 2. Results indicate that the coal is of Subbituminous C rank with heat value of 8290 Btu as received. The ash and sulfur content as received is 3.66 and 0.32 percent, respectively.

##### Estimation of Coal Resources

The term "coal resources" is defined as the estimated quantity of coal that is currently or potentially economically mineable. Resource estimates have been prepared for the Chromo/4 Study Site using standard procedures and are presented on Table 3.

The quantities shown are categorized as demonstrated resources and are the sum of measured and indicated resources. They contain coal for which estimates of rank, quality and quantity are known and coal for which estimates have been at least partly computed using reasonable geologic projections.


Table 3 shows coal reserves for the Knoblock coalbed which at the Chromo/4 Study Site is divided into three main sets of beds - the upper, middle and lower coalbeds. Because of their closeness, the quantities for the Upper Knoblock and the Middle Knoblock have been combined. The quantity for the Lower Knoblock is shown separately.

Nearly all of the study site is covered with less than 200 feet (61 m) of overburden above the Upper Knoblock (Plate 4). Table 3 divides the coal reserves of the Upper and Middle Knoblock coalbeds into quantities covered by set ranges of overburden thicknesses.

Two thicknesses of interburden, one below the Upper Knoblock and one split in the Middle Knoblock are not included in the stripping ratios shown in Table 3. This is noted in the footnotes section.

The interburden between the Middle and Lower Knoblock coalbeds averages about 40 feet (12.2 m) at the study site and quantities and stripping ratios have been figured separately for it.

R 45 E



## EXPLANATION

## OVERBURDEN ABOVE UPPER KNOBLOCK COALBED

- 0 TO 50 Feet
- 50 TO 100 Feet
- 100 TO 150 Feet
- 150 TO 200 Feet
- OVER 200 Feet
- Structure contour on top of Upper Knoblock Coalbed
- Contour showing depth to top of Upper Knoblock Coalbed
- OH 77-101 USBR Drill hole
- P 1455 Drill hole from USGS Miscellaneous Field Studies Map MF-817

SCALE OF FEET

NOTE  
Multiply feet by 0.3048 to obtain meters



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF RECLAMATION		
RESOURCE & POTENTIAL RECLAMATION EVALUATION		
CHROMO/4 STUDY SITE		
OTTER CREEK COALFIELD-MONTANA		
OVERBURDEN THICKNESS MAP KNOBLOCK COALBED		
GEOLOGY	PARISH	SUBMITTED
DRAWN	E. ALLSOP	RECOMMENDED
CHECKED		APPROVED
BILLINGS, MONTANA		APRIL 1978
		1305-600-148



REVISED: APRIL 18, 1978

Report of: Coal AnalysisDate April 3, 1978Job Number 61-114-1Sheet 1 of 1Report to: BUREAU OF RECLAMATION (1)  
P O BOX 2553  
BILLINGS MT 59103Sample Identification:

On March 15, 1978, this coal sample was delivered to our laboratory with instructions to perform the following analyses.

## TEST RESULTS:

Drill Hole : 77-101  
 Area : Otter Creek - Chromo 4  
 Depth, ft. : 143.9-149.7; 154.5-180.8; 182.0-188.9; 215.3-225.6  
 Coal Composite  
 Lab No. : 10472

Analysis	Proximate	Ultimate	Sulfur Forms	
% Moisture:			% Pyritic Sulfur:	
As Received	31.90	As Received	As Received	0.02
Air Dry Loss	18.98	Air Dry	Air Dry	0.02
Oven Dry Loss	15.95	Oven Dry	Oven Dry	0.02
% Ash:		% Hydrogen**:	% Sulfate Sulfur:	
As Received	3.66	As Received	As Received	0.01
Air Dry	4.52	Air Dry	Air Dry	0.01
Oven Dry	5.38	Oven Dry	Oven Dry	0.01
% Volatile:		% Nitrogen:	% Organic Sulfur:	
As Received	26.43	As Received	As Received	0.29
Air Dry	32.63	Air Dry	Air Dry	0.36
Oven Dry	38.81	Oven Dry	Oven Dry	0.43
% Fixed Carbon:		% Oxygen**:		
As Received	38.01	As Received	40.01	
Air Dry	46.90	Air Dry	28.58	
Oven Dry	55.81	Oven Dry	17.15	
% Sulfur:		**Includes coal moisture content in accordance with ASTM D3176.		
As Received	0.32			
Air Dry	0.39			
Oven Dry	0.46			
BTU, per pound:				
As Received	8,290	Note:		
Air Dry	10,233	Multiply feet by 0.3048 to obtain meters		
Oven Dry	12,175	Multiply Btu/pound x 1.80 to obtain kilogram-calories		
BTU, per pound:		/kilogram		
Ash, moist free	12,867			



RESOURCE AND POTENTIAL RECLAMATION EVALUATION  
OF  
CHROMO/4 STUDY SITE  
OTTER CREEK COALFIELD  
SECTION 4, T. 5 S., R. 45 E.  
COAL RESERVES, OVERBURDEN AND INTERBURDEN VOLUMES AND RATIOS,  
ACRES AND TONS PER ACRE

UPPER AND MIDDLE KNOBLOCK COALBEDS 1/					
Thickness of Overburden Ft.	Measured and Indicated Reserves		Overburden		Overburden Ratio 2/ Cubic Yards Per Ton
	Million Tons	Cubic Yards	Million	Cubic Yards	Acres
0-50	4.11	3.10		0.75	64
50-100	15.42	29.04		1.88	64,219
100-150	13.17	41.34		3.14	64,250
150-200	5.98	26.26		4.39	64,244
200+	1.22		6.74	5.52	64,301
Total	39.90	Total	106.48	Average 2.68 *	Total 621 Average 64,245

LOWER KNOBLOCK COALBED 3/					
Assumed Representative Thickness of Interburden Between Middle and Lower Knoblock Coalbeds	Measured and Indicated Reserves		Interburden Between Middle and Lower Knoblock Coalbeds		Interburden Ratio Cubic Yards Per Ton
	Million Tons	Cubic Yards	Million	Cubic Yards	
40	11.10		40.08		3.61
					621 17,874.40

## FOOTNOTES:

1/ Combined coal thickness of Upper and Middle Knoblock Coalbeds averages about 36.3 feet.  
2/ Interburden within the Upper and Middle Knoblock Coalbeds (two splits) varies from 5 to 11 feet (upper split) and 1 to 6 feet (lower split). This interburden is not included in the stripping ratios shown.  
3/ Thickness of Lower Knoblock Coalbed averages about 10.1 feet.

## English to Metric Conversions

Multiply	by	To Obtain
Feet	0.3048	Meter
Acre	0.4047	Hectare
Ton	0.9072	Tonne
Cubic Yard	0.7646	Cubic Meter

NOTES:  
Thickness of coal, overburden and interburden based on data from U.S.B.R. drill hole DH77-101 and drill holes P1455, P1052, P1039, P1047 and P1026 as shown on sheets 1 and 2 of U.S.G.S. Miscellaneous Field Studies Map MF-817 and plates 1 and 3 of this report.

\*Average shown is a weighted average based on the number of acres per individual ratio.



## LAND CLASSIFICATION

Land classification is a systematic appraisal of lands for a specific purpose. In this classification, lands were grouped in classes 1, 2, 3 or 6 based on their physical and chemical properties that related to their use for plant media in reclaiming surface-mined land. Specifications are on Table 4.

### Description of the Land

The principal natural land bodies consist of residual soils with some colluvial and alluvial soils of local origin. Within each soil type there is a range of physical and chemical properties. In this site colluvial soils are the most uniform and residual soils are the most diverse. The principal land condition represented by each soil group is described separately.

#### Alluvial Soils

The alluvial soils in this site are along the channel of small intermittent upland natural drains. Surface gradients range from 0 to 6 percent. The vegetative cover is largely mid and short grasses with scattered big sage and a few forbes.

Weakly developed loamy soil profiles are most common. This material is permeable, retains up to 2 inches (51 mm) of water per foot (.3 m), is well-drained, and is relatively stable. Precipitation enters and moves through this soil readily; therefore, surface runoff and erosion are minimal. The vertical water movement has usually leached the soluble salts below 24 inches (.6 m). Free carbonates occur just below the surface layer and the subhorizons are often saline and may be gypsiferous.

These soils are well suited for use as plant media. However, they occupy less than 1 percent of the study site.

#### Colluvial Soils

The colluvial soils are on footslopes of small natural drains and fans in the upland. They have developed under a mid and short grass plant association that has a moderate amount of big sage and forbes. Slope gradients range from 4 percent with many short steep slopes (35%) along natural drains.

Loamy and fine loamy soil profiles with moderate development are most common. The physical and chemical properties of the surface few inches are similar to the alluvial soils. The lower horizons and substrata have retained many of the physical and chemical properties of the parent material. This material is usually fine textured, slowly permeable and saline. It retains about 2 inches (51 mm) of available water per foot (.3 m). Surface runoff and erosion are in part slope dependent and range from low to moderate.

The upper 12 (.3) to 18 inches (.46 m) of soil are well suited for plant media. It may be placed at or near the surface of reconstructed profiles. Lower horizons are best suited for use immediately below the surface layer or deeper.

## Residual Soils

In this site the residual soils are on narrow ridges, knobs and steep and eroded slopes. The vegetative cover is variable and reflects the interaction of slowly permeable soils, slope gradient and the resultant erosion. Mid and short grasses are most common, but the number of forbes and salt-tolerant sedges and shrubs is moderate. Slope gradients range from 4 to over 35 percent. The rate of erosion is usually high.

Soil profile development is minimal and the physical and chemical properties below the surface 3 (.08) to 5 inches (.13 m) are similar to the underlying Fort Union Formation. This material is usually soft silty and clayey shales. This subsurface material is fine-textured, slowly permeable, commonly saline and sodic. Slick spots occur on smooth gentle slopes.

A composite of the surface 6 inches (.15 m), the approximate minimum stripping depth, will be fair-to-good for use as plant media. Residual soils represent 95 percent of the site. Raw shale exposures and rock outcrops are included in this soil type.

### Description of Classes

Class 1 land has no major soil and or topographic limitations. Topographically, this land is well-suited for stripping and stockpiling good quality overburden for use as plant media. The physical and chemical properties of this material make it suitable for use at or near the surface of reconstructed profiles. Land in this class is usually a good source of topdressing material. Excess material may be used in tracts with insufficient good-quality plant media.

Class 2 land has few soil and topographic limitations. Topographically this land can be stripped and stockpiled without special practices. The suitability of this material for use as plant media is reduced because of texture, permeability, salinity or quantity. Class 2 land has sufficient material for reclamation, but is only a fair-to-poor source of borrow material.

Class 3 land is limited by topography and soils. Special measures such as selective stripping and borrowing topdressing material for localized tracts will be required. Most Class 3 land will have sufficient suitable overburden for reclamation. However, the reclamation potential will be lower because of quantity, texture, permeability, salinity or sodicity. A high level of management will be required for optimum reclamation through revegetation.

Class 6 land does not have sufficient suitable overburden for reclamation. Material must be borrowed or the available material modified for optimum results. The topography and land conditions also limit stripping. Steep eroded slopes, bluff-forming sandstone and rock outcrops are common. However, selective stripping of the best material will reduce the amount of borrow required.

LAND CLASSIFICATION SPECIFICATIONS SURFACE MINE RECLAMATION  
 Suitability of Overburden for Revetation of Surface-Mined Areas  
 BLM/BR Cooperative Program EMRIA  
 Colorado Study Site

Table 4  
 United States  
 Dept. of the Interior  
 Bureau of Reclamation  
 July 1977

Overburden Characteristics	Basic Inform. Subclass & Defic.	Symbols		
		Class 1	Class 2	Class 3
<u>SOILS AND/OR BEDROCK</u>				
<u>Texture</u>	s	Sandy loams to clay loams.	Sandy loam to silty clay loam.	Loamy sand to clay.
Coarse	v		Sandy loam sufficiently coarse to slightly reduce productivity, moisture retention and may increase erosiveness slightly.	Loamy sand in sufficient quantity to moderately reduce productivity and moisture retention, and may increase erosiveness moderately.
Fine	h		Profile should have sufficient material for top dressing; clayey type materials that are moderately permeable should be placed below .15 m in the reconstructed profile.	Profile should have sufficient material for top dressing; placement of clay in reconstructed profile; permeable .25 m plus; slowly permeable .75 m plus.
<u>Depth</u>	d	1 m of overburden that is suitable for plant media.	.5 m of overburden that is suitable for plant media.	.25 m of overburden that is suitable for plant media.
<u>Sodicity</u>	a	SAR not to exceed 9.0 in clay textured material but may be 20.0 in loam sand. Values may be higher if compensated by adequate gypsum.		
<u>Salinity (m<sup>3</sup>/cm)</u>	s	Overburden with characteristics (chemical and physical) capable of producing an expected electrical conductivity at equilibrium with the natural precipitation must be readily available as follows:		
		Less than 4 m <sup>3</sup> /cm	Less than 8 m <sup>3</sup> /cm except the surface .25 m must be 4 m <sup>3</sup> /cm	Less than 12 except the surface .25 m must be 4 m <sup>3</sup> /cm
<u>Available Water Holding Capacity</u>	q	38 mm/.3m foot of overburden	.25 mm/.3m of overburden	.19 mm/.3m of overburden
<u>Hydraulic Conductivity</u>	p	Adequate to provide a well drained and aerated root zone and an infiltration rate adequate to prevent serious erosion.	Slightly restricted; movement of drainage water and aeration in the lower root zone will be reduced. Infiltration rate may be reduced and erosion hazard increase slightly.	Restricted in the lower root zone and internal drainage may limit choice of plant species. Restricted infiltration may create serious but controllable erosion hazard.
<u>Indurated Sandstone Stones and cobble</u>	x	Permissible stone in overburden that may be stockpiled and reused as surface soil 0 to .25 m 5%.	Permissible stone in overburden that may be stockpiled and reused as surface soil 0 to .25 m 10%.	Permissible stone in overburden that may be stockpiled and reused as surface soil 0 to .25 m 20%.
<u>Weatherability 1/</u>		Will break down readily upon exposure to the weather.	May require short period to break down upon exposure.	May require extended period to break down.
<u>Erodibility</u>	e	Slight.	Moderate, controllable with average management.	Severe but controllable with above average management and selective placement of overburden.
<u>TOPOGRAPHY 2/</u>	t			
<u>Slope</u>	g	Permissible surface gradient g = 0 to 12% with smooth slopes.	Permissible surface gradient g = 0 - 20%.	Permissible surface gradient g = 0 - 35%.
<u>Indurated Sandstone Massive and lenticular</u>	r	None.	1 to 5% of area.	5 to 20% of area.
<u>Cover</u>	c	Not applicable.		
<u>DRAINAGE</u>	d	(Present drainage conditions, surface and subsurface) are not a factor in this classification because of the anticipated land disturbance during mining. All soil properties evaluated to classify the land were also considered in evaluating material that may be placed in the subsurface drainage zone, but this evaluation did not affect the land classes.		
<u>Class 6</u>		Areas delineated in this class generally lack suitable material for stripping and stockpiling for surface use. One or a combination of the following deficiencies may result in the use of this class: (1) insufficient surface soil and bedrock of suitable quality at or near the surface; (2) topography which prevents general stripping and stockpiling; (3) rocklands with large amounts of massive indurated sandstone; (4) toxic overburden (soil and bedrock) on or near the surface. Reclamation of these lands will require material from outside the delineated area, from deep geologic strata, or special treatment of available material.		

1/ Applicable only to unweathered bedrock material.  
 2/ Not applicable to unweathered bedrock material.



### Methods and Procedures

The chemical and physical properties of soil profiles were evaluated in typical land areas and the land classes were delineated on photographs. Most profiles were sampled for testing in the soil laboratory. After the laboratory tests were completed, the land classes were finalized on reproducible drawings.

Standard laboratory procedures of pH, conductivity (salts), water movement, and soil stability were performed on all samples. Trace elements and heavy metals were determined on the bedrock cores.

Typical profile descriptions are recorded on Tables 6 and 8. Erosion conditions are shown on Tables 5 and 7. Tables 5 through 8 are in the Appendix.

### Results of Classification

Class 1 land occurs on 15 percent of the study site. This loamy textured material is of good quality and will be easily stripped and stockpiled.

Class 2 land makes up only 22 percent of this site. The major soil deficiencies are salinity and permeability. Sodium and rock are the other deficiencies.

Class 3 land occurs on 24 percent of the area. Soil deficiencies are sodicity, salinity and permeability. Some slick spots and rock and shale outcrops are included in this class. Some borrow will be required, but resurfacing material is adequate in most tracts.

Class 6 land represents 39 percent of the site. Small inclusions of good soil occur, but it is doubtful if they merit selective stripping.

The location and areal distribution of the land classes are shown on Plate 5. This drawing also shows the soil and topographic deficiencies.

Results of the screenable tests in the soil laboratory are recorded on Table 9 in the Appendix.

Plate 6 shows the location and the approximate depth of the topsoiling material. Plate 7 shows the depth, quantity and quality of material suitable for subsurface placement.

### Soil Inventory

The Powder River Area soil survey data is shown on Plate 8. The slope limitations and map symbols used by the Soil Conservation Service are shown. The acreage and percent of the study site occupied by each series is tabulated on this Plate.


### Reclamation Potential

The conditions in this site are adequate for reclaiming this land if the site is surface mined. The soil and topographic conditions are best suited for returning the site to range. Adding borrow material to class 6s and 6st tracts is necessary for satisfactory reclamation. However, profile enhancement and increased range production under post-mining conditions are possible on a limited amount of land.

To achieve maximum or optimum productivity levels under post-mining conditions, the following measures should be considered and used where applicable: (1) Add borrow material to some class 3s and 3st tracts, (2) Class 6 land must receive additional topdressing material and (3) strip and stockpile all suitable overburden for topdressing reshaped spoils. The quantity of this material would be determined by the post-mining goals of optimum or maximum productivity. Other measures that should be considered and used where applicable are (1) slope reduction and (2) reduce the number of moderately steep south and southwest facing slopes.

Regardless of the goal selected, the mining plan should also provide for the use of current approved land preparation and planting methods. Plant species, that are compatible with the land conditions, should be selected from an approved list.

The 40 acre tract now producing small grains can be returned to this capability level. There may be a few additional small tracts (10 to 40) acres that could be made suitable for small grain production in this site.



## EXPLANATION

SOIL PROFILE NOTES  
PROFILE REPRESENTS 5' DEPTH

## (3) SOIL PROFILE NUMBER

CL	2.8	2.8 EC mmhos/cm Sat Ext
	84-80	84 pH 1.5 Soil-Water Suspension
		80 pH Soil-CoCl <sub>2</sub> Suspension
Lt C		65 Hydraulic Conductivity - in/hr (Disturbed Sample)
Gr		24 Settling Volume

## SOIL PROFILE SYMBOLS

Cb	Cobble
Gr	Gravel
S	Sand
LS	Loamy Sand
SL	Sandy Loam
L	Loam
SIL	Silt Loam
SCL	Sandy Clay Loam
CL	Clay Loam
SiCL	Silty Clay Loam
SC	Sandy Clay
C	Clay
SiC	Silty Clay
Sh	Shale
Ss	Sandstone
F	Fine
Lt	Light
M	Medium
H	Heavy

INFORMATIVE SYMBOLS  
OVERBURDEN DEFICIENCIES  
(for plant media)

- o Salinity
- s Sodicity
- h Clay (very fine texture)
- v Coarse (very sandy texture)
- p Restricted permeability
- q Available moisture capacity
- d Depth of suitable overburden
- x Stoniness

## TOPOGRAPHIC DEFICIENCIES

- g Slope (including gradient and complexity)
- r Massive lenticular sandstone and/or Glacial erratics
- c Cover

## CONVENTIONAL AND SPECIAL MAP SYMBOLS

## LAND FEATURES

- Blowout
- ✗ Clay spot
- △ Gravelly spot
- ∅ Gumbo, slick or scaly spot (sodic)
- ≡ Dumps and similar nonsoil areas
- ▽ Rock outcrop (includes shale and sandstone)
- ▽ Baked rock - cinder (local name scoria)
- ↑ Slide or slip (ips point up slope)
- △ Stony spot, very stony spot
- Greasewood
- ✗ Soil Profile (check)


## WATER FEATURES

- ▽ Marsh or swamp
- Spring
- ∅ Well, artesian
- Well, irrigation
- ▼ Wet spot
- ✗ Grovel
- ✗ Mine
- Medium or small

## PITS

## DAMS

## Section 4, T 5 S - R 45 E

250 0 250 500  
SCALE OF METERS


UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF RECLAMATION  
RESOURCE & POTENTIAL RECLAMATION EVALUATION  
CHROMO/4 SITE  
OTTER CREEK COALFIELD - MONTANA

## SEMI-DETAILED LAND CLASSIFICATION

LANDS - M B WARD	SUBMITTED -
DRAWN BY E. ALLSOP	RECOMMENDED -
CHECKED -	APPROVED -
BILLINGS, MONTANA	MARCH 1978

1305-600-149





## EXPLANATION

DEPTH OF TOPSOILING MATERIAL  
MATERIAL FOR USE ON OR NEAR THE SURFACE

	ACRES
[Solid black square]	0 - 0.1
[Grid pattern square]	0.1 - 0.2
[Dotted circle square]	0.2 - 0.3
[Zip-a-tone square]	0.3 - 0.4
	210.3
	117.6
	224.6
	68.5

Section 4, T. 5 S. - R. 45 E.

250                    0                    250                    500                    750  
[Scale bar with arrows at 0 and 750]

SCALE OF METERS

TOTAL ADDITIONAL SUITABLE MATERIAL

(0.6)

Material over the amount indicated by the zip-a-tone symbols  
Best use below 0.1 meters




UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF RECLAMATION  
RESOURCE & POTENTIAL RECLAMATION EVALUATION  
CHROMO/4 SITE  
OTTER CREEK COAL FIELD - MONTANA  
TOPSOILING MATERIAL


LANDS H. B. WARD SUBMITTED  
DRAWN LE. ALLSOP RECOMMENDED  
CHECKED APPROVED  
BL. LINGS MONTANA MARCH, 1976 1305-600-150




## EXPLANATION

MATERIAL SUITABLE FOR SUBSURFACE PLACEMENT  
QUALITY OF MATERIAL

Good




Fair



Poor



NS (Not Suitable)



Material to 3 meters is suitable for use at or near the surface.

DEPTH TO MATERIAL FOR SUBSURFACE PLACEMENT 6'<sup>1/2</sup>

## NOTE

Usable material for subsurface, as used in this report includes that portion of the overburden (soil mantle and bedrock) that should be placed  $\frac{1}{2}$  below the primary plant root zone in reconstructed profiles. It contains no known toxic elements but may be clayey, sandy or highly saline. However, the soluble salts will leach from material subjected to downward movement of natural precipitation.

$\frac{1}{2}$  Unless modified by leaching, mixing or other measures.


## INFORMATIVE SYMBOLS

OVERBURDEN DEFICIENCIES  
(for plant media)


- a Salinity
- s Sodicity
- h Clay (very fine texture)
- v Coarse (very sandy texture)
- p Restricted permeability
- q Available moisture capacity
- d Depth of suitable overburden
- x Stoniness

## TOPOGRAPHIC DEFICIENCIES

- g Slope (including gradient and complexity)
- r Massive lenticular sandstone and/or Glacial erratics.
- c Cover







## SOIL SERIES

## SLOPE - %

Bc	Bew silty clay	0 - 2
Be	Bew silty clay	2 - 4
Ca	Cabba association	15 - 50
Ec	Elsa silt loam	8 - 15
El	Elsa silt loam	15 - 45
Fd	Farland silt loam	2 - 4
Hf	Haversan soils, channeled	
Ho	Hesper silty clay loam	2 - 4
Hp	Hesper silty clay loam	4 - 8
Hs	Hopley and Relan loams	4 - 8
Hw	Hydro-Arvada complex	2 - 8
Mg	Midway - Elsa association	8 - 35
Mw	Midway and Elsa rocky soils	35 - 75
Nh	Nihill - Elsa association	8 - 15
Ro	Remmit - Ocean Lake fine sandy loams	8 - 25
Ta	Thurlaw silty clay loam	4 - 8

Section 4, T. 5 S. - R. 45 E.

250 0 250 500 750 SCALE OF METERS



UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF RECLAMATION  
RESOURCE & POTENTIAL RECLAMATION EVALUATION  
CHROMO/4 SITE  
OTTER CREEK COAL FIELD - MONTANA  
SOIL SURVEY MAP

LANDS - H. B. WARD - SUBMITTED -  
DRAWN L. E. ALLSOP - RECOMMENDED -  
CHECKED - APPROVED -



## APPENDIX

DETERMINATION OF EROSION CONDITION CLASS  
SOIL SURFACE FACTORS (SSF)

By	Date
Location	Location
(B) 4-7-27	4-7-27
Treatment affecting the SSF	

SITUATION	TOTAL	44	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	0	No visual evidence of movement	Some movement of soil particles	Moderate movement of soil is visible and recent. Slight terracing generally less than 1" in height.	Occurs with each event. Soil and debris deposited against minor obstructions.	Subsoil exposed over much of area, may have embryonic dunes and wind scoured depressions
SOIL MOVEMENT	SOIL SURFACE FACTORS	SURFACE ROCK	ROCK PELTING	PELTING	PATTERN	PATTERNS	PATTERN	PATTERN															
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20			
ACCUMULATING IN PLACE	ACCUMULATING IN PLACE	ACCUMULATING IN PLACE																					
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20			
LITTER	LITTER																						
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20			
ROCK	ROCK																						
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20			
PELTING	PELTING	PELTING																					
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20			
PATTERNS	PATTERNS	PATTERNS																					
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20			
RILLS	RILLS																						
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20			
GULLIES	GULLIES	GULLIES																					
0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20			

Table 5

(Instructions on reverse)

U. S. DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

VEGETATION-SOIL DESCRIPTION

1. State <u>Mont.</u>	2. District <u>2</u>	3. Planning Unit <u>28</u>	4. Vegetation-Soil Unit	5. Soil Map Sym- bol	6. Surname	7. Date <u>7/1 mo - yr</u>
8. Area <u>78</u>	9. County <u>P. River</u>	10. Location Sec. - <u>4</u> -, T. <u>5</u> -, R. <u>45</u> <u>E</u>	11. Photo No.	12. Writeup No.	13. File No.	14. Parent Rock Formation
15. Formation Name <u>Fort Union</u>	16. Surface Conditions (percent)	17. Land Conditions				18. Landform <u>Coldwater</u>
19. Slope (percent) <u>2-4%</u>	20. Aspect <u>E</u>	21. Elevation - <u>972 m</u>	22. Present Erosion Type <u>Sheet</u>	23. Hydrologic Group <u>41 - Class Mod</u>		
24. Precipitation (in) <u>12-16"</u>	25. Temperature 1st , 2nd , 3rd , 4th - - Air - - Soil	26. Frost-free Days <u>120 &gt; 28°</u>	27. Drainage Class <u>Mod.</u>	28. Infiltration <u>Slow</u>	29. Percolation <u>Slow</u>	30. ERD <u>.43 m</u>
32. Hori- zon- thick- ness <u>m</u>	33. Color DRY MOIST	34. Texture MOTTLING	35. Structure	36. Clay Films	39. Roots	40. Stones % VOL
A 2 0 - 0.5	(D) 104R 4/3 (H) " 4/3	-	Sil	mod mild	(D) So (M) Vfr	-
A B .05 - .10	(D) 104R 4/2 (H) " 4/2		< CL	C1p1/ m/bk	(D) Sb (M) Vfr	-
B 2t .10 - .30	(D) 104R 5/3 (H) " 5/2		> CL	C2p1/ c2bk	(D) H (M) Vfr	-
B 3 .30 - .40	(D) 104R 5/3 (H) " 5/3		CL	C2p1/ c2bk	(D) H (M) Vfr	-
C ca .40 - .56	(D) 104R 4/3 (H) " 5/3		CL	C1p1/ c1bk	(D) H (M) Vfr	-
C 2 .56 - 1.1	(D) 104R 6/4 (H) " 6/3		CL	Massive (H) fr	-	-
C 3 1.1 - 1.5	(D) 104R 6/4 (H) " 6/3		CL	" (D) H (M) Vfr	-	-
BR Series Correlated stratified surface shales & carbonaceous materials						
40 - .56 horizon contains thin intertongues of sandstone						
SL - 1.1 - 1.5						
Interf. of B2t may vary from heavy clay to light clay depending on location at position. Up to 35% thick shale may be in place.						

Table 6

**DETERMINATION OF EROSION CONDITION CLASS**  
SOIL SURFACE FACTORS (SSF)

By	Date
	1/17/72
Location	44° 17' S. R. 45 E
Treatment affecting the SSF	

SOIL MOVEMENT		SOIL SURFACE		SOIL ROCK		SOIL TAILING		SOIL PEDDLES		SOIL RILLS		SOIL GULLIES	
No visual evidence of movement		Some movement of soil particles		Moderate movement of soil is visible and recent. Slight terracing generally less than 1" in height.	(5)	Moderate movement is apparent, deposited against obstacles	(7)	Extreme movement apparent, large and numerous deposits against obstacles	(9)	Very little remaining (use care on less productive sites)	(11)	Subsoil exposed over much of area, may have embryonic dunes and wind scoured depressions	(14)
0 1 2 3		4 5		0 1 2 3	4 5	0 1 2 3	4 5	0 1 2 3	4 5	0 1 2 3	4 5	0 1 2 3	4 5
MOVEMENT		SURFACE		ROCK		TAILING		PEDDLES		RILLS		GULLIES	
+				+		+		+		+		+	
No visual evidence of flow patterns		Some rills in evidence at infrequent intervals over 10'		Some rills in evidence at infrequent intervals over 10'	(7)	Well defined, small, and few with intermittent deposits	(7)	Rills 1/4" to 6" deep occur in exposed places at approximately 10' intervals	(7)	Rills 1/4" to 6" deep occur in exposed area at intervals of 5 to 10'	(9)	Flow patterns contain silt and sand deposits and alluvial fans	(12)
0 1 2 3		4 5 6		0 1 2 3	4 5 6	0 1 2 3	4 5 6	0 1 2 3	4 5 6	0 1 2 3	4 5 6	0 1 2 3	4 5 6
FLOW PATTERNS				FLOW PATTERNS		FLOW PATTERNS		FLOW PATTERNS		FLOW PATTERNS		FLOW PATTERNS	
+				+		+		+		+		+	
No visual evidence of gullies		A few gullies in evidence which show little bed or slope erosion. Some vegetation is present on slopes.		Gullies are well developed with active erosion along less than 10% of their length. Some vegetation may be present.	(6)	Gullies are numerous and well developed with active erosion along 10 to 50% of their length or a few well developed gullies with active erosion along more than 50% of their length	(6)	Gullies are numerous and well developed with active erosion along 10 to 50% of their length or a few well developed gullies with active erosion along more than 50% of their length	(6)	Gullies are numerous and well developed with active erosion along 10 to 50% of their length or a few well developed gullies with active erosion along more than 50% of their length	(6)	Gullies are numerous and well developed with active erosion along 10 to 50% of their length or a few well developed gullies with active erosion along more than 50% of their length	(6)
0 1 2 3		4 5		0 1 2 3	4 5	0 1 2 3	4 5	0 1 2 3	4 5	0 1 2 3	4 5	0 1 2 3	4 5
GULLIES				GULLIES		GULLIES		GULLIES		GULLIES		GULLIES	
+				+		+		+		+		+	
SITUATION	TOTAL												

Table 7

U. S. DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

## VEGETATION-SOIL DESCRIPTION

Table 8

1. State <u>Montana</u>	2. District <u>02</u>	3. Planning Unit <u>08</u>	4. Vegetation—Soil Unit <u>—</u>	5. Soil Map Sym- bol <u>—</u>	6. Surname <u>—</u>
8. Area <u>78</u>	9. County <u>P. River</u>	10. Location Sec. <u>4</u> , T. <u>5</u> , R. <u>45E</u>	11. Photo No <u>—</u>	12. Write-up No <u>—</u>	13. File No <u>—</u>
15. Formation Name <u>Fort Union</u>	16. Surface Conditions (percent) Stone <u>—</u> , Rock <u>20%</u>	17. Land Conditions Alkaline <u>—</u>	18. Landform <u>Residue /</u>	19. Slope (percent) <u>15-35%+</u>	20. Aspect <u>E</u>
		21. Elevation <u>4750'</u>	22. Present Erosion Type <u>Rill &amp; Gull'q</u>	23. Hydrologic Group <u>B</u>	
		24. Precipitation (in.) <u>12.16"</u>	25. Temperature 1st, 2nd, 3rd, 4th <u>—</u>	26. Frost-free Days <u>— 100 - &gt; 28°</u>	27. Drainage Class well Drained
		32. Hori- zon- Thickness <u>mm</u>	34. Color Matrix <u>DRY</u>	35. Texture MOTTLING	36. Structure 37. CONSIS- TENCY DRY MOIST
		38. Clay Films	39. Roots	40. Stones % VOL.	41. REACTION ( $pH$ )
					42. BOUNDARY
A <sub>1</sub>	0-12	(D) 109R <u>5/2</u> (H) " <u>4/2</u>	—	rnibk / mlgc.	(D) 50 (H) vir
AC	13-20	(D) 109R <u>6/2</u> (H) " <u>5/2</u>	—	L	(D) 50 mlbk / mlgc.
C	20-35	(D) 109R <u>7/2</u> (H) " <u>4/2</u>	—	L	(D) 50 Massive mlgc.
CA	35+	Soil is consolidated sandy shales on sandstone. Roots running parallel to surface. Effective rooting depth is averaging 7 inches. Surface is scrubland with <u>Yucca</u> vegetation, several without surface protection. Pine trees grow along upper slope of cut. Exposed sandstone E' shales are approximately 60% of area.	—	—	—

UNITED STATES - DEPARTMENT OF THE INTERIOR - BUREAU OF RECLAMATION - UPPER MISSOURI REGION  
SOIL LABORATORY - MILES CITY, MONTANA

UNIT SOIL SCIENTIST CHROMO/4

PROJECT 10-4 LOCATION- SECTION 4 T. 55 R. 45-46  
DATE 11/17/77

LAB NO.	PROFILE NO.	DEPTH METERS	TEXTURE FIELD LAB	pH 1-5 CaCl <sub>2</sub>	SET. VOL. ml	EC		FRAG. HYD. COND.		SODIUM ABSORPTION RATIO		GYP. REQ. me/100g	PARTICLE SIZE PERCENTAGE			HCL %
						1-5 SAT.	1-5 EXT.	8 hr in./hr	24 hr in./hr	TSC me/l	Cat. Mg me/l		SAND	SILT	CLAY	
1	1	0-4.5	>CL	8.7	7.4	26	0.20	0.14	0.12							+
2		4.5-1.1	CL	8.3		36	2.00	10.8	0.24	0.24						+
3		1.1-1.5	CL	8.7	8.2	50	11.5	9.0	0.06	0.06	92.0	63.0	13.8	-4.8		+
4		1.5-2.1	CL	8.6	8.2	100	1.90	7.0	0.00	0.03						+
5		2.1-2.7	SCL	9.2	8.2	140	5.4	0.75	8.5	0.00	0.00					+
6		2.7-3.0	SCL	9.1	8.1	96	5.4	0.75	7.5	0.00	0.00					+
7	2	0-3.0	CL	8.6	7.6	23	1.2	0.16	1.72	1.60						+
8		3.0-6.1	>CL/C	9.3	8.0	36	2.2									+
9		6.1-1.2	>CL	8.8	8.3	50	12.0									+
10		1.2-1.7	CL	9.0	8.5	42	11.5									+
11		1.7-2.3	>CL	8.3		37	16.0	27.0	0.24	0.24	27.0	97.0	24.9	-2.8		+
12		2.3-2.7	>CL	8.2		35	15.0	22.5	0.11	0.13						+
13		2.7-3.0	>CL	8.5		45	15.0	32.0	0.07	0.08						+

DOUBLE LINE RECORDS THE CONTACT BETWEEN SOIL MANTLE AND BEDROCK

UNITED STATES - DEPARTMENT OF THE INTERIOR - BUREAU OF RECLAMATION - UPPER MISSOURI REGION  
SOIL LABORATORY - MILES CITY, MONTANA

CHROMO/4

UNIT SOIL SCIENTIST WYATT

PROJECT 4 LOCATION- SECTION 4 T. 55 R. 45 E

LAB NO.	PROFILE NO.	DEPTH METERS	FIELD	LAB	PH	SET. VOL.	EC	FRAG. HYD. COND.		SODIUM ABSORPTION		GYP. REQ. me/100g	PARTICLE SIZE PERCENTAGE	HCl - %		
								SAT.	EXT.	8 hr in./hr.	24 hr in./hr.	Ca/Mg me/l	SAR	SAND	SILT	CLAY
3	14	0.30	<CL		7.6			1.0								
						23	0.13			2.00	1.84					
15	30.91	CL		9.1	7.8	22	0.19			0.34	0.36					
16	91-1.5	L		9.6	8.2	50	3.0			0.03	0.02					
17	1.52-2.1	FSL		9.5	8.2	44	4.1	0.55	7.0	0.06	0.04	70.0	13.8	16.5	-5.2	
18	2.1-2.6	FSL		9.2	8.2	50	0.65	9.0	0.68	0.64						
19	2.6-3.0	FSL		9.2	8.1	50	4.2	0.65	9.0	0.82	0.80					
21	20	0.30	CL		8.4			1.0		2.64	2.32					
						24	0.13									
21	30.91	CL		9.6	8.1	50	2.5			0.12	0.13	25.0	4.8	13.5	-3.2	
22	91-1.4	<CL		9.5	8.5	33	6.4	0.90	9.0	0.02	0.01	90.0	31.0	14.75	-4	
23	1.4-2.0	<CL		9.3	8.6	32	8.6	1.50	15.0	0.00	TR					
24	2.0-2.4	<CL		9.2	8.6	40	9.8			1.70	18.0	TR	TR			
25	2.4-3.0	<CL		9.0	8.5	70	9.5	1.70	18.0	0.52	0.48					

UNITED STATES - DEPARTMENT OF THE INTERIOR - BUREAU OF RECLAMATION - UPPER MISSOURI REGION  
 SOIL LABORATORY - MILES CITY, MONTANA

 UNIT CHROMO/4 PROJECT 1000 LOCATION- SECTION 4 T. 55 R. 45 E DATE 1/17/55

LAB NO.	PROFILE NO.	DEPTH METERS	TEXTURE	pH	SET. VOL.	EC	FRAG. HYD. COND.		SODIUM ABSORPTION RATIO		GYP. REQ. me/100g	PARTICLE SIZE PERCENTAGE	HCL %
							SAT.	EXT.	8 hr in./hr	24 hr in./hr	Cat. Mg me/l	SAR	
5	2.6	0.46	CL	8.0		23	1.0	0.13	1.88	1.72			+
27	.46-.76	CL		8.7	7.8	21	1.0	0.13	0.84	0.72			++
28	.76-1.5	>SL		9.4	8.0	29	1.6	0.20	1.52	1.44			++
29	1.5-2.1	CL		9.6	8.3	130	4.4	0.60	4.0	0.00	0.00	40.0	++
30	2.1-2.6	CL		9.4	8.3	90	5.5	0.75	9.0	0.00	0.00	40.0	++
31	2.6-3.0	CL		8.3	40	13.5	2.70	15.0	0.34	0.36			+
6	32	0.46	CL	8.3		22	1.2	0.16	1.12	1.10			++
33	.46-.91	CL		9.1	7.6	20	2.6	0.32	0.68	0.60			++
34	.91-1.4	>CL		8.5		29	9.0	1.5	12.0	0.36	0.32		++
35	1.4-1.8	CL		8.6	7.9	24	7.4	1.1	12.5	0.74	0.62		++
36	1.8-2.4	CL		8.7	8.0	27	6.8	1.0	14.0	1.08	0.88		++
37	2.4-2.9	SL		9.5	8.2	130	5.4	0.75	9.0	TR	0.02		+

UNITED STATES - DEPARTMENT OF THE INTERIOR - BUREAU OF RECLAMATION - UPPER MISSOURI REGION  
 SOIL LABORATORY - MILES CITY, MONTANA

Chromo/4

UNIT SOIL SCIENTIST PROJECT 11/17/77 LOCATION- SECTION 4 T. 55 R. 4.52

LAB NO.	PROFILE NO.	DEPTH METERS	TEXTURE		PH	SET. VOL. ml	EC	FRAG. HYD. COND.		SODIUM ABSORPTION		GYP. REQ. me/100g	PARTICLE SIZE PERCENTAGE	HCL %
			FIELD	LAB				1-5	SAT. EXT.	8 hr in./hr	TSC me/l	Ca/Mg m <sub>2</sub> /l		
7	3.8'	0-30	C'		8.5		1.9	0.90	0.12	1.40	1.16			+
		3.9	30-76	CL	9.2	7.8	2.3	1.8	0.23	0.18	0.15			+
43	.76-1.4	CL			8.9	8.1	2.8	1.0	9.5	1.28	0.21			+
41	1.4-2.0	CL >CL			8.9	8.1	2.4	1.1	12.3	0.00	0.00			+
42	2.0-2.6	CL			9.4	8.1	2.9	0.6	6.0	0.09	0.05			+
43	2.6-3.0	CL			9.7	8.0	2.8	0.34	0.00	0.00				+
		2												+
44	0-46	CL			7.7		2.4	0.9	0.12	1.28	1.04			+
45	.46-.91	CL			8.4		2.1	0.75	0.10	0.68	0.56			+
46	.91-1.2	SCl			8.7	7.6	2.0	0.75	0.10	1.42	1.20			+
47	1.2-1.5	SCl			9.1	7.9	2.4	1.40	0.18	0.46	0.42			+
48	1.5-2.1	FSL			9.3	7.9	2.4	1.40	0.18	3.04	2.72			+
49	2.1-2.6	SCl			9.6	7.8	5.4	1.60	0.22	1.00	0.92	16.0	2.4	+
50	2.6-3.0	SCl			9.6	7.9	11.5	1.60	0.20	0.00	0.02			-

UNITED STATES - DEPARTMENT OF THE INTERIOR - BUREAU OF RECLAMATION - UPPER MISSOURI REGION  
SOIL LABORATORY - MILES CITY, MONTANA

CHRONO/4

UNIT SOIL SCIENTIST W.H. STONE PROJECT 4 LOCATION- SECTION 4 T. 55 R. 55 E

DATE 11/27

LAB NO.	PROFILE NO.	DEPTH	TEXTURE	pH	SET. VOL. ml	EC	SODIUM ABSORPTION RATIO			GYP. REQ. me/100g	PARTICLE SIZE PERCENTAGE			HCL %			
							1-5	SAT. EXT.	8 hr in./hr		TSC me/l	Ca/Mg. me/l	SAR	SAND	SILT	CLAY	
51	0-30	<u>SCL</u>	<u>SL</u>	7.6	22	0.50			5.60	8.00				76	4	20	+
52	30-91	<u>LFS</u>		8.5	19	0.10			2.48	1.80				77			+
10	53	0-30	L	8.2	21	0.12			2.00	1.64				78			+
54	30-91	<u>CL</u>		8.8	7.6	1.9	0.90		1.36	1.08				79			+
55	91-1.5	<u>CL</u>		8.8	27	5.2	7.0	0.00	0.00	70.0	39.6	6.84					+
56	1.5-2.1	<u>SCL</u>		9.6	8.0	1.20	0.72	0.00	0.00				79				+
57	2.1-2.7	<u>SL</u>		9.5	7.9	140	3.00	0.00	0.00				79				+
58	2.7-3.0	<u>SCL</u>		9.4	7.8	1.20	0.40	0.00	0.00				79				+
11																	
59	0-30	L		8.3	22	0.12			1.64	1.24				79			+
60	30-91	<u>CL</u>		8.9	22	1.20	0.16	0.62	0.52				79			+	
61	91-1.4	<u>CL</u>		9.5	8.1	75	4.05	5.0	0.00	0.00				79			+
62	1.4-2.0	<u>CL</u>		8.6	8.0	40	1.42	14.25	0.72	0.60	142.5	56.0	15.5	80			+
63	2.0-7.6	<u>CL</u>		2.1	8.1	50	1.0	14.0	0.40	0.35				80			+
64	2.6-3.0	<u>CL</u>		8.5	10.0	1.90	16.0	0.33	0.28				80			+	

UNITED STATES - DEPARTMENT OF THE INTERIOR - BUREAU OF RECLAMATION - UPPER MISSOURI REGION  
SOIL LABORATORY - MILES CITY, MONTANA

**CHROMO/4**

PROJECT 4 LOCATION- SECTION 4 T. 5 S. R. 45 E.

DATE 11/17

SOIL SCIENTIST	LAB NO.	PROFILE NO.	DEPTH METERS	TEXTURE		PH	SET. VOL. ml	EC	FRAG. HYD. COND.	SODIUM ABSORPTION RATIO		GYP. REQ. me/100g	PARTICLE SIZE PERCENTAGE	HCL %		
				FIELD	LAB					SAT. 8 hr in./hr	24 hr in./hr	Cat. Mg. me/l	SAR			
12	65	0-30	FSL	SCL	SCL	7.2	20	0.75	5.60	3.00				68	12 20	
13	30-76	C4/SCL	SCL	9.4	7.7	60	2.50							60	14 26	
17	76-1.1	SCL		9.7	8.1	330	0.32	0.03	0.01					44.		
18	1.1-1.7	SCL		9.7	8.3	260	0.62	4.60	0.00	0.00				7.		
19	1.7-2.3	SCL		9.6	8.2	160	0.95	6.00	4.25	0.00	0.00			-		
21	2.3-2.7	SCL		9.4	8.0	140	0.77	5.60	4.5	0.00	0.00			-		
21	2.7-3.0	SCL		9.5	8.0	140	0.70	5.20	4.5	0.00	0.00			-		
13	72	3-46	>CL		8.5			1.60						+		
73	46-1.1	>CL			8.1			2.3	0.20	0.72	2.88			+		
—	1.1-1.2	S	No Sample					2.7	1.20	7.2	0.60	1.24			44.	
74	1.2-1.7	CL			8.4			4.1	1.50	10.0	0.20	0.30	100.0	42.0	12.6 - 4.0	
75	1.7-2.3	C:			8.5			7.0	11.00	2.00	14.0	0.05	0.07		44.	
76	2.3-2.7	CL			8.2			7.0	13.50	2.40	13.0	0.20	0.20		+	
77	2.7-3.1	CL			8.2			7.0	13.50	2.40	18.0	0.00	0.02		-	

UNITED STATES - DEPARTMENT OF THE INTERIOR - BUREAU OF RECLAMATION - UPPER MISSOURI REGION  
SOIL LABORATORY - MILES CITY, MONTANA

## CHROMO/A

UNIT CHROMATOGRAPH PROJECT 4 LOCATION- SECTION 4 T. 55 R. 45E  
SOIL SCIENTIST Y

PROIECT

UNITED STATES - DEPARTMENT OF THE INTERIOR - BUREAU OF RECLAMATION - UPPER MISSOURI REGION  
SOIL LABORATORY - MILES CITY, MONTANA

Chemona

UNIT SCIENTIST MM PROJECT 4 LOCATION- SECTION 4 T-5 S.R. 45-2 DATE 11/177

LAB NO	PROFILE NO.	DEPTH METERS	TEXTURE	pH	SET. VOL.	EC	SAT. EXT.	8 hr 24 hr in./hr	TSC me/l	CAT Mg me/l	SAR	GYP. REQ me/100g	PARTICLE SIZE PERCENTAGE			
													1-5 ml	1.00	2.00	8.00
1.1	89	0.46	CL	8.1												
1.2	90	0.46-1.1	CL	9.4	7.9	45	0.44	2.1	0.05	0.01	3.1.0	4.0	12.1	-1.6		
1.3	91	1.1-1.7	CL	8.8	8.3	34	1.00	2.00	15.0	0.74	2.24					
1.4	92	1.7-2.1	CL	8.7	8.5	32	1.00	2.22	16.0	0.72	1.84					
1.5	93	2.1-2.7	CL	8.3				1.00								
1.6	94	2.7-3.0	CL	8.5				3.6	3.60	16.0	0.44	0.88				
									13.50							
									41	2.40	14.0	0.50	0.80			
1.7	95	0-3.0 < CL		8.6	7.5	24	1.80									
1.8	96	3.0-7.6	CL	9.1	8.1	70	0.90	6.40								
1.9	97	7.6-1.2	CL	9.1	8.5	70	9.00	1.50	14.0	0.07	0.06	150.0	42.5	21.2	-2.0	
1.10	98	1.2-1.7	CL	8.9	8.4	64	14.0	2.40	17.5	0.00	0.02					
1.11	99	1.7-2.1	CL	8.8	8.4	45	16.0	3.60	20.0	0.24	0.04					
1.12	100	2.1-2.7	L	9.2	8.6	37	1.50	8.00	20.0	0.27	2.36					
1.13	101	2.7-3.0	CL	9.1	8.5	100	1.20	15.0	0.50	0.05						



MS28-19  
(3/76)

MISSOURI SOURIS PROJECTS OFFICE  
SOIL AND WATER LABORATORY  
BUREAU OF RECLAMATION  
BISMARCK, NORTH DAKOTA  
SOIL ANALYSIS DATA SHEET

OWNER'S CARD

BLM LIBRARY  
SC-324A, BLDG. 50  
DENVER FEDERAL CENTER  
P. O. BOX 25047  
DENVER, CO 80225-0047

OFFICE	DATE RETURNED

(Continued on reverse)

**DATE DUE**

SAYLOR

PRINTER IN N.Y.A.

Bureau of Land Management  
Library  
Bldg. 50, Denver Federal Center  
Denver, CO 80225

